

## Operating Guide

# AK-SM 800A R4.0 Change Log

ID	Work Item Type	Title
908613	Feature	Update security - AK-SM 800A 'Session Control'
1005862	Product Backlog Item	Update firewall scripts for session control
1008092	Product Backlog Item	Security scan validation
1142579	Product Backlog Item	Support to SvW/SvB5 on Session Control for default Strict Mode Popup
<b>New features and updates</b>		
546590	Feature	Reserved File-System Access for SvW Application use
817360	Feature	Increase # of evap nodes under suction group
1151591	Feature	Support for Carlo Gavazzi EM530 and EM511
1040111	Product Backlog Item	Update XML 1.0 documentation for session control
955259	Feature	Stop Danux downgrade (due to differing SOM Module types)
971384	Product Backlog Item	Update SI Dead-band values (improved history view for Sensor Inputs)
1091843	Product Backlog Item	Implement comm loss detection and recovery
1009016	Product Backlog Item	Implementation of Modbus/IP (compatible AK-CC55 controls only)
<b>Bugs and Corrections</b>		
688847	Bug	Ensure protection against parsing device files > 50000 character limit
715128	Bug	XML function file_load_status causes reset
777768	Bug	Local Display Does Not Graph Converted G3P Celsius Values Correctly
826489	Bug	General 15min sample rate history not working
845540	Bug	DGS Offline/Online Local Discrepancy -not working on local screen
857021	Bug	Reported issue with DNS operation
865548	Bug	AK-SM 800A with EKC 202D2 sensor offset value not applying
865560	Bug	AK-SM 800A 3.2.6 schedules night setback not available for pack controller 3.1.11 works
865940	Bug	Local UI - History - History config parameters listing not available for WattNode MB device
1024613	Bug	Square D Powerlink G3 Light Panel not detected by scan.
1039012	Bug	AK-XM 208C module not fully implemented
1144797	Bug	Bug: Time changes are not reflecting properly in PI200 connected Danmax controllers
1147386	Bug	Bug: Date & Time changes are restarting the system manager randomly
1220704	Bug	AK-SM 800A gets wrong IP of 28.8.0.0
1220711	Bug	Energy Alarms become unconfigurable
1232892	Bug	Enabling and then (after ~30 sec) disabling MODBUS TCP will cause ALL existing Modbus networks to lock up and report offline
1155355	Feature	MAC addressing of unit on startup

**Danfoss A/S**

Climate Solutions • danfoss.com • +45 7488 2222

Any information, including, but not limited to information on selection of product, its application or use, product design, weight, dimensions, capacity or any other technical data in product manuals, catalogues descriptions, advertisements, etc. and whether made available in writing, orally, electronically, online or via download, shall be considered informative, and is only binding if and to the extent, explicit reference is made in a quotation or order confirmation. Danfoss cannot accept any responsibility for possible errors in catalogues, brochures, videos and other material. Danfoss reserves the right to alter its products without notice. This also applies to products ordered but not delivered provided that such alterations can be made without changes to form, fit or function of the product.

All trademarks in this material are property of Danfoss A/S or Danfoss group companies. Danfoss and the Danfoss logo are trademarks of Danfoss A/S. All rights reserved.