



IECEx Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	DK/ULD/QAR12.0002/11	Page 1 of 2
QAR Free Ref. No.:	4791032700	Status:Issued
Details of change:	Reassessment Audits	Date of issue:2024-04-11
Location(s) audited:	Danfoss A/S Nordborgvej 81 DK-6430 Nordborg Denmark Danfoss Poland Sp z.o.o., UL. Chrzanowska 5 05-825 Grodzisk Mazowiecki Poland Danfoss Ltd No.9 Quanhui Road Wuqing Development Area 301700 Tianjin China	Valid until:2027-03-30 Audit date:2024-04-04
Issuing ExCB:	ULD - UL Solutions (Demko)	
Manufacturer:	Danfoss A/S, Nordborgvej 81, 6430 Nordborg	
Location of Manufacturer:	Denmark	
Product information:	Poland - Thermostats, Pressure Switches and Electrically Operated Coils Denmark - Pressure transmitters and Gas detection units China - Electrically operated coils & pressure transmitters	
Type of protection:	Poland: Thermostats, Pressure Switches and Electrically Operated Coils Increased Safety "e", Intrinsic Safety "i" and Encapsulation "m" Denmark: Pressure transmitters and Gas detection units Flameproof "d", Increased Safety "e", Intrinsic Safety "i" and Encapsulation "m" China: Electrically operated coils & pressure transmitters Increased Safety "e", Intrinsic Safety "i" and Encapsulation "m"	
Related QARs:		
DK/ULD/QAR12.0002/00	DK/ULD/QAR12.0002/01	DK/ULD/QAR12.0002/02
DK/ULD/QAR12.0002/03	DK/ULD/QAR12.0002/04	DK/ULD/QAR12.0002/05
DK/ULD/QAR12.0002/06	DK/ULD/QAR12.0002/07	DK/ULD/QAR12.0002/08
DK/ULD/QAR12.0002/09	DK/ULD/QAR12.0002/10	
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:		
IECEX BVS 18.0044X issue: 0	IECEX BVS 18.0044X issue: 1	IECEX ITS 12.0070X issue: 0
IECEX PRE 15.0029X issue: 0	IECEX PRE 15.0029X issue: 1	IECEX PRE 15.0029X issue: 2
IECEX ULD 12.0005X issue: 0	IECEX ULD 12.0005X issue: 1	IECEX ULD 12.0005X issue: 2
IECEX ULD 12.0005X issue: 3	IECEX ULD 12.0005X issue: 4	IECEX ULD 12.0005X issue: 5
IECEX ULD 12.0005X issue: 6	IECEX ULD 12.0005X issue: 7	IECEX ULD 14.0001X issue: 0
IECEX ULD 14.0001X issue: 1	IECEX ULD 14.0001X issue: 2	IECEX ULD 14.0001X issue: 3
IECEX ULD 14.0001X issue: 4	IECEX ULD 14.0001X issue: 5	IECEX ULD 14.0001X issue: 6
IECEX ULD 14.0001X issue: 7	IECEX ULD 14.0013X issue: 0	IECEX ULD 14.0013X issue: 1
IECEX ULD 14.0013X issue: 2	IECEX ULD 14.0013X issue: 3	IECEX ULD 14.0013X issue: 4
IECEX ULD 17.0043 issue: 0	IECEX ULD 18.0004X issue: 0	IECEX ULD 18.0004X issue: 1
-- Continued on the next page		



IECEx Quality Assessment Report Summary

QAR Ref. No.: **DK/ULD/QAR12.0002/11**

Page 2 of 2

Related Certificates for
previous versions (continued):

IECEx ULD 18.0004X issue: 2
IECEx ULD 21.0024X issue: 1

IECEx ULD 18.0004X issue: 3
IECEx ULD 21.0024X issue: 2

IECEx ULD 21.0024X issue: 0
IECEx ULD 23.0014U issue: 0

Comments: This is a Limited Scope QAR. Please contact ExCB for additional information.