


Danfoss

INSTRUCTIONS AKS Solder Instruction

060R9515




Danfoss
AB60312.10

2 - 5 sec.



10 - 15 sec.



Danfoss
AB60311.10

060R9515

Danfoss
AB60312.11

Max 100°C
(212°F)

