



免責事項 DISCLIMER

本製品は爆発防止機器として設計されていません。下記事項を厳守して下さい。
下記事項が遵守されなかつた場合に発生した偶發的、必然的問題は弊社の免責事項と致します。

1 記事項が厳守されなかつた場合に発生した偶発的、必然的問題は弊社の免責事項と致します。

- ・製品は可触不可な位置に取り付け、外部から衝撃が加わらないように保護をして下さい。
また一度でも衝撃が加わった製品は絶対にユニットに組み込まないで下さい。
- ・ユニットの状態で製品が作動することを必ず検査して下さい。
- ・コイルに電気信号を入れて10分経過しても製品が作動しない場合はコイルに流れる電流を緊急停止させる制御又は、それが出来るような回路を常設して下さい。
- ・配管後は検査圧力1MPaにて2g/year相当の検知能力となる気密検査を必ず実施して下さい。

THE COMPONENTS ARE NOT DESIGNED AND CONSTRUCTED AS EXPLOSION-PROTECT EQUIPMENT.
PLEASE ADHERE TO THE FOLLOWING MATTERS. THE ACCIDENTAL AND INVITABLE THAT OCCURRED WHEN THE BELOW MATTERS WERE NOT STRICTLY OBSERVED WILL BE OUR DISCLAIMER.

- ・MAKE SURE TO INSTALL THE PRODUCT AT INACCESSIBLE POSITION AND TO AVOID ANY OF THE MECHANICAL IMPACT FROM OUTSIDE. AND THE PRODUCT, RECEIVED SUCH A MECHANICAL EVEN JUST ONE TIME, SHALL NOT BE EMPLOYED IN THE UNIT.
- ・MUST BE INSPECTED THAT THE PRODUCT OPERATES IN A COMPLETED STATE AS A UNIT.
- ・IF THE PRODUCT DOES NOT OPERATE EVEN AFTER 10 MINUTES ELAPSING BY PUTTING AN ELECTRIC SIGNAL IN THE COIL, PLEASE CONTROL TO STOP THE CURRENT FLOWING THE COIL BY EMERGENCY STOP, AND/OR PLEASE BE SURE TO INSTALL A CIRCUIT THAT CAN DO IT.
- ・MUST GIVE THE VALVE AN AIRTIGHT TEST AFTER PIPING.
- ・BE SURE TO AIR TIGHT INSPECTION WITH DETECTION CAPACITY EQUIVALENT TO 2 [g/year] AT INSPECTION PRESSURE 1 [MPa] AFTER PIPING.

Approved by 	Date JUN 13 2019	Name 四方弁本体 4-WAY REVERSING VALVE BODY	
Designed by 	Scale 1:2	Catalog Number STF-H0954	Drawing Number N-HV-95023-B
Drawn by 	SAGINOMIYA SEISAKUSHO, INC.		

DANFOSS

B 2020. 9. 18 仕様欄変更、注記追加 三留
- 2019. 12. 19 免責事項変更(No. S-FD001→No. S-FD001-1) 三留
A 2019. 9. 13 使用周囲温度及び許容流体温度の下限変更 三留