

Software Change Note

Product: Vacon NXL series
Software type: Brake Control Application
Old software id: ALFIFF30V202
New software id: ALFIFF30V203

Mal-functions in the old software:

1. Not possible to edit option board parameters

Changes in the new software:

1. Changed to firmware NXL 1.19

Field update:

It is recommended to update the application if the above-mentioned malfunctions are faced.

System software requirements:

NXL00005V250 or newer

Manual:

UD01014b