

Software Change Note

Product: Vacon NXS/NXP series
Software type: Fire Mode PID Application
Old software id: ASFIFF11V209
New software id: ASFIFF11V210

Mal-functions in the old software:

1. Was not possible to change the PID reference (R 3.4) from keypad.

Changes in the new software:

1. Corrected problem with PID Reference

Field update:

It is recommended to update the application if the above-mentioned functions are needed.

System software requirements:

NXS00001V169

NXP00002V170

Manual:

UD00752