ENGINEERING TOMORROW



Case story | VLT® Lift Drive LD 302

# Fast retrofit for maximum elevator uptime

The senior residents in an apartment block in Saltcoats, Scotland were confined to their homes until Northern Industrial found a rapid fix for their faulty elevator. Luckily Danfoss VLT® Lift Drive LD 302 ensures that fast retrofit of an elevator drive is possible with an off-the-shelf solution.





## Acute fix needed

The comfortable lives of senior residents in a block of apartments in Saltcoats, Scotland, were recently perturbed by a malfunctioning elevator. Northern Industrial, a leading Danfoss Drives elevator specialist, was called in to fix the problem, which was particularly acute as many of the residents found it difficult or even impossible to leave the building without using the elevator.

Service repair a costly affair

When the engineers from Northern Industrial arrived at the Saltcoats apartments, they found the problem was that the drive for the elevator motor had failed and that it was a type that had long been obsolete. With no like-for-like replacement available anywhere in the market and no spare parts to effect a repair, returning the elevator to service could have been a long and costly affair.


In the past, the only way to fix a problem of this type would have been to replace the obsolete drive with a standard variable speed drive, which would then need to be customized with option modules to run elevator applications. As standard drives aren't dedicated for elevator applications, they are complicated to install. It requires a lot of time and effort to transfer parameters and programs due to the closed architecture typically used in elevator control systems.

"Fitting the new Danfoss drive was an easy and fast task, as the drive set-up system and documentation use industry-standard elevator terminology. In addition, the drive's dedicated elevator design made it easier to configure, which meant that we didn't have to replace the whole controller, and that saved us a lot of time and

Ben Fordham, Installing Engineer, Northern Industrial

# VLT® Lift Drive LD 302

To address this common problem with ageing elevator installations, Danfoss has introduced its VLT® Lift Drive. This drive has been designed from the outset to be easy to install and set up in elevator applications, and to be compatible with almost any type of elevator control system. And it's available off the shelf, which makes it possible to keep lift downtime to an absolute minimum.



Installing the Danfoss VLT® Lift Drive was straightforward due to designed-for-the-job elevator functionalities.

# An ideal choice for retrofit

The Danfoss drive boasts open architecture with the simple menu structure written in plain, easy-tounderstand language. These factors made it an ideal choice for the engineers from Northern Industrial to install as a replacement for the old drive that had failed in the Saltcoats apartments.

Fitting the Danfoss VLT® Lift Drive proved to be as straightforward as expected and, after it had been installed, it was found to provide a much smoother ride than the old drive it replaced. It was also much quieter in operation – which is always a bonus in residential locations – as it has a specially controlled cooling fan that runs only when needed.



# Saves time and money

Upon completing the retrofit, Ben Fordham, the engineer from Northern Industrial who installed the drive, explained: "Fitting the new Danfoss drive was an easy and fast task, as the drive set-up system and documentation use industry-standard elevator terminology. In addition, the drive's dedicated elevator design made it easier to configure which meant that we didn't have to replace the whole controller, and that saved us a lot of time and money."

# No time for downtime

Elevators provide an essential service in residential, medical, commercial, business and manufacturing buildings, so when they break down, there are enormous pressures on engineers to fix them as soon as possible. Using designed-for-the-job elevator drives from Danfoss offers a simple solution to this sometimes difficult and costly problem. The off-the-shelf Danfoss VLT® Lift Drive requires minimal customization and can save thousands of pounds in repair costs – not to mention offering quick and easy installation that guarantees the elevator will be up and running in the shortest time possible!



Ben Fordham of Norther Industrial fitting the drive on site

### **Northern Industrial**

A Danfoss Drives partner and Danfoss VLT® Lift Drive specialist in the UK. www.nicontrols.com

### Saltcoats, Scotland

The small harbour town dates from the late 17th century with later alterations, and at low tide fossilised trees can be seen on the harbour floor. It was in Saltcoats in 1793 that Betsy Miller, the first woman ever to have become a registered ship's captain, was horn

Saltcoats today is much better known for its picturesque harbour and golden, sandy beaches set around Irvine Bay.

Danfoss Drives, Ulsnaes 1, DK-6300 Graasten, Denmark, Tel. +45 74 88 22 22, Fax +45 74 65 25 80, drives..danfoss.com, E-mail: info@danfoss.com

Danfoss can accept no responsibility for possible errors in catalogues, brochures and other printed material. Danfoss reserves the right to alter its products without notice. This also applies to products already on order provided that such alterations can be made without subsequential changes being necessary in specifications already agreed.

All trademarks in this material are property of the respective companies. Danfoss and the Danfoss logotype are trademarks of Danfoss A/S. All rights reserved.