

Danfoss Comfort Controls
2004.11.01

**Tech Note on RA 2000 sensors:
Marking of date of production**



Dear Madam and Sir,
This is to announce that the location where you find the date of production on RA 2000 sensors is being changed from week 46. New location is circled in red.

*The code is according to standard:
"A" means first two weeks of the year, "B" is the second two weeks etc.
"4" is the year 2004*

Below is complete list of code numbers concerned.

RA2000 IF m pinol.	013G2910
RA2000 FF m pinol.	013G2912
RA2000 IF	013G2914
RA2000 FF	013G2916
RA PUP IF	013G2920
RA PUP FJF	013G2922
RA-SNAP 0 HV	013G2940
RA/VL IF	013G2950
RA/VL FJF	013G2952
RA/V IF	013G2960
RA/V FJF	013G2962
RA-SNAP MAX	013G2970
RA-SNAP MAX	013G2972
RA-SNAP	013G2975
RA-SNAP MAX	013G2977
RA-MAX IND.	013G2978
RA-SNAP D	013G2980
RA-SNAP D	013G2982
RA-SNAP NL	013G2990
RA-SNAP NL	013G2992
SERVICE KIT	013G4017
SERVICE KIT	013G4018
SERVICE KIT	013G4019
RA-DUSA PU	013G8240
RA-DUSA IF	013G8250
RA-DUSA FJF	013G8252

Linkto Intranet:

http://cd.trv.danfoss.net/pcmfiles/1/trv/tech_sup/tech_notes/tech_note_front.asp?MenuUID=B3F40081-0B83-489C-86A7-215337B3E5CB

Published by CD-ST, Claus Christensen